

Oil Field Environmental Incident Summary

Incident: 20150420095702 **Date/Time of Notice:** 04/20/2015 09:57
Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Name: CLEMENS 24-7H
Field Name: DIMMICK LAKE **Well File #:** 17182
Date Incident: 4/19/2015 **Time Incident:** 11:00 **Facility ID Number:**
County: MCKENZIE **Twp:** 151 **Rng:** 96 **Sec:** 7 **Qtr:** SW SE
Location Description: Immediately adjacent to the south side of the pad.

Submitted By: Lewis Schoenberger **Received By:**
Contact Person: Lewis Schoenberger
PO BOX 51810
MIDLAND, TX 79710-1810

General Land Use: Pasture **Affected Medium:** Topsoil

Distance Nearest Occupied Building: 0.5 Mile
Distance Nearest Water Well: 0.5 Mile

Type of Incident: Treater Leak

Release Contained in Dike: No **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels				

Brine

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 8/3/2016 **Clean Up Concluded:** 6/3/2015

Risk Evaluation:

None

Areal Extent:

approximately 140 yards by 40 yards

Potential Environmental Impacts:

None

Action Taken or Planned:

Oil impacted vegetation will be collected for appropriate disposal.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 4/20/2015 ***Status:*** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary to ensure proper cleanup.

Date: 4/22/2015 ***Status:*** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 17:51 p.m. The weather was clear, 57 °F, with the wind from the southeast 10-15 mph. Vegetation on the pad slope and in the stubble field has been sprayed with oil out to the gravel road. The field does not appear to be seeded. Nothing has been cleaned up in the field or on the slope. More followup needed to verify the cleanup. 47.90329; - 103.00581

Date: 5/12/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 16:08 p.m. The weather was cloudy, 63°F, with the wind from the southeast 10-20 mph. The sprayed area is still visible in the field, but field has been worked up and seeded. The side of dike is still stained.

Date: 5/28/2015 **Status:** Correspondence

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Requested clearance samples and documentation.

Date: 6/25/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 10:22 a.m. The weather was sunny, 75°F, with the wind from the southeast 5-10 mph. The area sprayed has crop growing. No further follow-up needed.